Kodak i800 Series Scanners Software Release Notes

Version CD 3.20 Summary

Purpose of Release: This release was created to provide Windows VISTA support and correct an issue with TWAIN driver behavior after an Image Address overflow.

Date: January 18th, 2008

Versions:

TWAIN driver: 6.65.9

ISIS driver: 1.0.10708.24001

Scan Validation Tool: 5.24
Firmware: 3.10
STI driver: 2.5 (signed)

Color Tables: 1.0

New Features from CD 3.15:

- 1. Add Vista Support for both TWAIN and ISIS
- 2. Add Japanese Installer

Improvements from CD 3.15:

- 1. TWAIN: Correctly handling of Image Address overflow
- 2. TWAIN: Fixed an issues with multifeed and jam not reporting correctly on the first document scanned

Version CD 3.15 Summary

Date: May 10th, 2006

Versions:

TWAIN driver: 6.65.2

ISIS driver: 1.0.10412.6001

Scan Validation Tool: 5.24 Firmware: 3.8

STI driver: 2.5 (signed)

Color Tables: 1.0

New Features from CD 3.10:

1. (None)

Improvements from CD 3.10:

1. TWAIN: Fixed the imprint string and image address between scan sessions not being changed as requested.

Version CD 3.10 Summary

Date: Feb 1st, 2005

Versions:

TWAIN driver: 6.41

ISIS driver: 1.0.10412.6001

Scan Validation Tool: 5.20 Firmware: 3.1

STI driver: 2.5 (signed)

Color Tables: 1.0

New Features from CD 2.6:

1. TWAIN/ISIS: Added grayscale output.

- 2. TWAIN/ISIS: Added uncompressed color output.
- 3. TWAIN/ISIS: Added support for Check Digit.
- 4. TWAIN/ISIS: Added Small/Large Comic 180 and Cinema 180 printer fonts.

Improvements from CD 2.6:

1. ISIS: Fixed setting of IA print string.