

## Kodak i5x50 Series Scanners Windows Drivers Release Notes

### ISIS Version 2.0.11906.12001 Summary

**Purpose of Release:** This release updates the ISIS driver package to version 2.0.11906.12001 which updates the testappn.exe to the latest version.

This driver should only be installed if there is a need for the latest version of the testappn.exe program. For all other use cases, the ISIS driver included in CD 5.7 should be installed.

**This host software release is not approved for use on i5000 scanner models.**

**Prerequisite:** i5250, i5650, i5850, i5650S and i5850S

**Date:** July 10, 2024

**Versions:**

ISIS driver: 2.0.11906.12001

**Recommended Scanner Firmware:**

Scanner Firmware Version: 07.02.00

**Driver Tested on Operating Systems:**

WINDOWS 10 (32-bit) – 22H2 & 23H2

WINDOWS 10 (64-bit) – 22H2 & 23H2

WINDOWS 11 (64-bit) – 23H2

**Supported Models:**

Kodak i5250, Kodak i5650, Kodak i5850, Kodak i5650S, Kodak i5850S

**New Features for V2.0.11906.12001:**

1. Updated testappn.exe package to latest release

**Notes:**

1. This driver package has not been tested with i5200, i5600, i5800 and MUST not be used with the Kodak i5200V or i5600V models.

**Known Issues:** (none)