

Kodak i700 Series Scanners ISIS Driver Update Release Notes

ISIS Driver Version eki700_2.1.11111.15006 Summary

Date: 11/15/2011

New Features from version 2.1.11004.30002:

1. (none)

Improvements from version 2.1.11004.30002:

1. ISIS- Moved endorser counter update code to occur after cleanup.
2. PR#16639 - ISIS error when simplex scanning and color toggle set to both sides
3. ISIS#34062 - ScanPlus - Blank page are not deleted if blank deletion is set up in scanner settings (Kodak i780) Modified the driver to include TAG_DETECTBLANKIMAGE. Values are TAG_DETECTBLANKIMAGE_OFF and TAG_DETECTBLANKIMAGE_ON. This will match the QD spec by allowing the host to query support and enable/disable BPD
4. PR#17909 – Corrected issue with not being able to rotate the rear image to 90/270 rotations when front is also enabled.
5. ISIS- Corrected issue with “Can’t connect on Citrix”